

Save and Seal Shower and Balcony Repair Waterproofing

With over years of combined trade experience Save & Seal offers its customers confidence, service and piece of mind. Knowing that their job will be done right the first time. Our broad industry knowledge stems from both commercial and residential construction, where we have worked in all forms of waterproofing, sealing, grouting, screeding, tiling, balcony repairs and tiling. From small tile repair to full bathroom re-grouting we can do it all.

The Save & Seal team are well-known skilled industry professionals, qualified and licensed to repair and re-seal any bathrooms. Whilst learning our trades at other companies over the years, a group of trade professionals came together bringing with them the best experience, skill and knowledge available. Together with a huge understanding and respect for its clients Save & Seal prides itself on its punctuality, reliability and customer service. From our first initial visit to quote a job right through the repair process we treat our clients home as if it were our own! Clean presentable trade technicians, clean fully stocked vehicles with materials and tools required for each job and drop sheets to protect our client's homes and furnishings. Minimal fuss. Maximum effort.

It's because of this that we can not only claim but also proudly say that we actually work with some of Melbourne's largest builders, Real Estates, Plumbers and Hotel Chains. Providing service, warranty and repairs across Melbourne. No gimmicks, cheap promises or slogans just honesty and integrity... That's what we offer at Save & Seal.

Leaking showers are a common problem in many houses and apartments. Save and Seal cover all aspects of shower repairs ranging from Missing Grout Cracked Tiles or Drummy and Hollow sounding Tiles.

Save and Seal can Tile your Shower with a selection of tiles including : Marble Granite Limestone Terracotta Mosaic Porcelaine Ceramic to mention but a few.

If you have Tiles Lifting or Grout Missing Save and Seal can cover a wide scope of repairs from Stopping your Leaking Shower without Removing Tiles to a complete Bathroom overhaul or Renovation.

If you notice grout missing or cracked in sections of your shower tiled walls, it could be due to movement or water saturation (trapped water) behind the tiles or brick walls.

Save and Seal can remove your Old Tiles Screed your Shower Base and apply between x2 and x4 coats of a flexible Waterproof Membrane depending on the background surface we are working too.

Epoxy seals are commonly used to Grout Swimming Pools because of its longer lasting results, thus being a great option for waterproofing your shower and in many cases without Removing Tiles.

Shower Bases can vary from being Tiled Bases or Ceramic or even Plastic Poly Marble Base. Save and Seal can also remove and rebuild it for you (Custom made) if required.

Whatever your concern or desired outcome, We at Save and Seal pride ourselves in excellent communication on all jobs providing dust sheets and photographs throughout various stages of our jobs.

To Discuss Further Please Call us Now on: 0412 998 003

Leaking balconies can be a serious danger, especially if it's been leaking slowly for some time before you notice it.

The most common cause of balcony issues is that the waterproofing membrane has failed and the joists are suffering gradual leak damage and rot. If the balcony is left to deteriorate for a long period of time you are looking at many problems, such as:

Decay and rot spreading down external walls

Discolouration on walls or ceilings

Electrical issues

Collapsing balcony

Contact Save and Seal now on 0412 998 003 or Contact us here.

It's always a challenge when you're trying to determine where the balcony leak/leaks are coming from. Here are a few handy hints from us when looking:

Is the balcony drain blocked, or has some kind of plumbing failure occurred in the area?

Has the joinery of the door leading out to the deck failed?

Is the leak visible on the under side of the balcony?

Has the tile grouting putrefied and is the water leaking through a join in the waterproofing membrane under the tiles?

Is the water running back across the joists under the deck from outside edge?

Is the base of the cladding touching the deck? If so water can potentially back up into the bottom plate of the timber wall frame.

Has the waterproofing membrane been correctly installed underneath the door frame to prevent wind driven rain getting up underneath the door and down into the wall below?

Is the water coming down from the roof and running down the external walls?

Any cracks in the plaster cladding around the balcony or external walls in the area?

Is the tiled area sealed correctly?

If you have managed to tick any of these please call Save and Seal for a free quote on 0412 998 003 we will send out one of our highly trained technicians to assess the situation and give you options on rectifying the problem.

Causes of Leaking Balcony:

The reason most balconies leak is that the membrane has failed due to improper application or the wrong product was used. We have seen countless membranes fail mostly due to the application being done in a way in which the product was not allowed to work to its full capacity, for example, the application was not thick enough, or the membrane has not been allowed enough time to cure. These are some of the most common reasons why balcony membranes fail.